

## FEDERAL and AMERICAN EAGLE 45 AUTO PRODUCT SAFETY WARNING

### Immediate Action Required


Certain lots of recently manufactured 45 Auto ammunition may contain an incorrect propellant charge. **Use of product from these lots may result in firearm damage and possible serious injury.**

**DO NOT USE PRODUCT FROM THE FOLLOWING LOTS:**

**38X628 through 38X765**

**38T401 through 38T414**

If you have in your possession any 45 Auto with the following brand names and part numbers, check to see if your ammunition package contains the above lots: American Eagle<sup>®</sup> (AE45A, AE45N1, or AE45A250), Champion<sup>™</sup> (WM5233), GoldMedal<sup>®</sup> (GM45B), Hi-Shok<sup>®</sup> (45C, 45D) and Federal<sup>®</sup> Personal Defense<sup>®</sup> (C45C, C45D). Example below:



**THIS WARNING APPLIES ONLY TO THE LOTS LISTED ABOVE.**

If you possess ammunition from any of these lots, or have questions concerning this warning, please contact us at **1-800-831-0850** or **1-800-322-2342** and ask for Product Service. Federal will provide replacement product and will cover the cost of returning the affected product.

We apologize for any inconvenience this may cause.